

## Challenge

### Issue

The existing bitumen lining in an effluent dosing pit was failing, resulting in acid attack on exposed concrete. If waste dosing pit leaks, the plant is at risk for environmental fines.

### Goals

Remove failed lining; repair and recoat to provide a positive seal on internal surfaces.

### Root Cause

Acid levels degraded bitumen lining over time.

## Solution

### Preparation

- High-pressure water blast to remove failing bitumen lining on concrete and steel surfaces.
- Blast surfaces to SP10 for metal and CSP#3 for concrete

### Application

1. Apply **ARC 791** to patch degraded concrete
2. Apply **ARC S1HB** by heated plural component spray to a dry film thickness of 2.5 mm (80 – 100 mils)

## Results

### Client Reported

New lining continues to be free of flaws or failure as of 9+ years.

Note: **ARC S1HB** was available for many years as a custom product, but is now available commercially.



Water blasting and grout patched concrete



Applying **ARC S1HB** by heated plural component spray



Finished surface